

Bypass Port-911 Engine Case

For all instances where the oil pump is being replaced, this bypass modification is necessary. Passage size is 11mm.

Failure to perform this operation will result in the engine case filling with oil when the pressure is above the opening pressure of the oil bypass spring.

